

C:\Users\j... \AppData\Local\Temp\... \View... \Layers\CLDS_Gen3_011207

Municipal Boundaries	Water Service Areas
Urban Growth Boundary	Floodplains
Wastewater Facilities	Wetlands
BTG	Parcels
OLDS Areas Evaluated	Bodies of Water
Sewer Service Areas	


1000 0 1000 2000 Feet

WELL RESULTS


- Wells with no Bacteria Detected and Nitrate Levels < 5 mg/l
- Wells with no Bacteria Detected and Nitrate Levels 5-10 mg/l
- Potential Malfunction Wells with no Bacteria Detected and Nitrate Levels > 10 mg/l
- Wells with Bacteria Detected and Nitrate Levels < 5 mg/l
- Wells with Bacteria Detected and Nitrate Levels 5-10 mg/l
- Potential Malfunction Wells with Bacteria Detected and Nitrate Levels > 10 mg/l

SANITARY SURVEY RESULTS

- Confirmed Malfunction
- Suspected Malfunction
- Potential Malfunction
- No Detected Malfunction



RAPHO TOWNSHIP
 971 North Colebrook Road
 Manheim, PA 17545
 Lancaster County



ACT 537 SEWERAGE FACILITIES PLAN
Inventory of OLDS & Private Wells
Map 3
 Prepared by **ARRG**